



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
CLIFFE ROAD	o/s 5	Dead	TR: Felling-Dead - Dead	Sorbus aria	o/s 5 in same location, new 800mm pit, (same as felled tree)	Crataegus 'Pauls Scarlett'
CLIFFE ROAD	o/s 33	Dangerous	TR: Felling - structural integrity, significant decay to main stem, dieback throughout the crown. - Structural integrity compromised, significant decay to main stem, dieback throughout the crown.	Prunus serrulata	o/s 33 in original location, 800mm tree pit.	Malus 'Rudolph'
CLIFFE ROAD	o/s 76	Dangerous	TR: Felling- - Historically topped, stem decaying, dead branch stubs only remaining, very poor specimen	Prunus serrulata	Between 74-76 in verge (relocated 1m to between 2 properties)	Malus 'Rudolph'
CLIFFE ROAD	o/s 3 (facing 34)	Damaging	TR: Felling - Kerb disrupted by buttress rooting immediately behind	Sorbus aria	Plant in new 800mm pit o/s 3, 3m uphill from junct Walkley Terrace, (same as felled tree)	Malus 'Rudolph'
CLIFFE ROAD	o/s 54	Stem only remains	TR: Felling- - Stem only remaining - cropped/topped at 1.7m, stem decaying, very poor specimen	Prunus serrulata	o/s 5 in same location, new 800mm pit, (same as felled tree)	Crataegus 'Pauls Scarlett'
CLIFFE ROAD	No Tree to be removed	No Tree at location	TR: Replanting- Crataegus 'Pauls Scarlett'SCH 20 - Plant in new 800mm pit o/s 27-29	No Tree to be removed	o/s 27-29	Crataegus 'Pauls Scarlett'